

Page 1 of 4

Report number: YZJC23X0607-964



# Product name: imitation Rittal cabinet

Entrusting unit: Linyi Wangsong Electric Co., Ltd.I

nspection Category: Commissioned Inspection



Beijing yingzhun Testing Technology Service Co., Ltd

Floor, No. 46 Yudai River East Street, Tongzhou District, Beijing If you have any objections to the test report, you should submit it to the testing unit within 2 days from the date of receipt of the report. Overdue requests will not be accepted.



### Page 2 of 4

### Report number: YZJC23X0607-964

011		国际互认 检测 TESTING CNASL13496			
Page 2 of 4		AF THE NEW	Report n	umber: YZJC23X0607-964	
	Requester	Linyi Wangsong Electric Co., Ltd.			
	Entrusting unit address	No. 502, Zaoyuan Town Industrial Park, Lanshan District, Linyi City, Shandong Province			
	production unit			W-REAL	
	Production unit address	No. 502, Zaoyuan Town Industrial Park, Lanshan District, Linyi City, Shandong Province			
	sample name	Gabinete imitación Rittal	marca comercial	Electricidad Wangsong	
	A THE REAL	1	Number of samples	1	
	Specifications and models	2100x1200x600mm	Sample grade	Qualified product	
identify category		Commissioned inspection	Sample status	intact	
Sample arrival date		June 02, 2023	Completion Date	June 07, 2023	
1	testing base	GB/T 4208-2017 "Enclosure Protection Level (IP Code)"			
Те	est conclusion	The test results of the sample inspection items all meet the test standards.			
Sample Pictures		いたのでは、 などのでは、 ないのでは、 ないのでいのでは、 ないのでいのでは、 ないのでいのでは、 ないのでいのでは、 ないのでいのでは、 ないのでは、 ないのでは、 ないのでい			
ļ	W. H. T	(Special seal for inspection) Issuance date: June 7, 2023			
Add	ditional information	The commissioned inspection is only responsible for the incoming samples and does not bear ot her joint and several liabilities.			
Ap	oproved by: - Mog	Reviewer: 7	Editor:	李雪晴	

If you have any objections to the test report, you should submit it to the testing unit Within 2 days from the date of receipt of the report. Overdue requests Will not be accepted.



Page 3 of 4

#### Report number: YZJC23X0607-964

## **Test results**

serial number	Test items	skills requirement	Test results	Individual judgment
1	Protection level	IP55	Meet the requirements	qualified
2		he test metal wire with a diameter of 1.0mm shall not enter the she Il and be connected with the live parts. keep enough clearance		qualified
3	dust-proof	It is not possible to completely prevent dust from entering, but the amount of dust that enters must not affect the equipment. normal operation of the equipment and shall not affect safety	Meet the requirements	qualified
4	water proof	Spraying water in all directions on the enclosure has no harmful effects	Meet the requirements	qualified
5	Waterproof test conditions	Nozzle inner diameter: 6. 3mm	大-接接到	qualified
6		Water flow: (125±0625)L/min	- Sf-	qualified
7		Water pressure: Adjust according to the specified water flow rate;		qualified
8		The central part of the main water flow: 2. 5m away from the nozzle, a circle with a diameter of approximately 40mm;	lite sample.	qualified
9		Water spraying time per square meter of shell surface: about 1 minute	Water ingress, compliance with requirements	qualified
10		Test time: at least 3min	-FE-PE-	qualified
11	大性植制	Distance from nozzle to shell surface: 2. 5m~3m		qualified
	· · · · · · · · · · · · · · · · · · ·	Distance from nozzle to shell surface: 2. 5m~3m	接情謝	1372 ,

Floor, No. 46 Yudai River East Street, Tongzhou District, Beijing If you have any objections to the test report, you should submit it to the testing unit within 2 days from the date of receipt of the report. Overdue requests will not be accepted.



Page 4 of 4

Report number: YZJC23X0607-964

## Precautions

1. This institution guarantees the impartiality of the test, keeps the test samples provided by the client confidential and protects the ow nership.

2. This report is invalid if it is not signed by the issuing person or stamped with the institution 's special red inspection and testingseal .

3. The report is invalid if it is altered, and the copy is invalid if it is not re-stamped with the agency 's special red inspection and testing seal.

4 The test data and results in this report are only responsible for the samples submitted for inspection.

5 Each page of this report is an integral part of the report. If the user extracts certain pages separately, it may lead to misunderstanding or use for other purposes and the resulting consequences.

This organization does not bear corresponding legal responsibility for the consequences.

Floor, No. 46 Yudai River East Street, Tongzhou District, Beijing If you have any objections to the test report, you should submit it to the testing unit within 2 days from the date of receipt of the report. Overdue requests will not be accepted.